



RIVERFRONT PARK BRIDGES

INSPECTION AND ANALYSIS

HOWARD STREET SOUTH CHANNEL BRIDGE

NOVEMBER 14, 2014 | Final Report

HOWARD STREET SOUTH CHANNEL BRIDGE

November 14, 2014

Prepared for

City of Spokane

Steve Hansen, Senior Engineer

Prepared by

Kpff Consulting Engineers

Marijean Frymoyer, PE

Project Engineer / Inspection Team Leader

Sub-consultants

SWCA Environmental Consultants

Eileen Heideman

Architectural Historian

Table of Contents

Bridge Inspection and Analysis Report

1. Bridge Description
2. Document Review
3. Evaluation Procedures
4. Evaluation Findings
5. Conclusions and Recommendations
6. Permits and Cultural Resource Requirements

Appendix A

Bridge Inspection Form

Key Photographs

Bridge Component Labeling System

Appendix B

Bridge Improvement Details

Cost Estimate

Appendix C

Photograph Log

Photograph Contact Sheet

1. BRIDGE DESCRIPTION

The Howard Street South Channel Bridge was built in 1931 as a vehicle bridge. The bridge currently carries only pedestrian traffic over the south channel of the Spokane River. The center of the bridge is fenced off to reduce the live load on the bridge. The four span cast in place reinforced concrete bridge has span lengths of 48 feet, 48 feet, 48 feet, and 41 feet.

This bridge is programmed for replacement. Accordingly our task as inspectors was to determine if we concur with the established sentiment regarding this bridge's current state of deterioration, remaining life, and to develop concepts and costs for replacement.




Figure 1: Aerial view of the Howard Street South Channel Bridge

2. DOCUMENT REVIEW

In preparation for this evaluation, Kpff reviewed the following documents related to the Howard Street South Channel Bridge:

- Bridge Plans (general plan and elevation and structural details)
- Downtown Spokane Streetcar Alternative Analysis – Howard Street Corridor Bridge Analysis
- Previous routine inspection reports
- 2012 Interim underwater inspection report

3. EVALUATION PROCEDURES

Kpff was tasked to inspect the primary structural components. However, the bridge is already known to contain severely defective structural girders and the City has already determined they wish to replace this bridge. Accordingly our evaluation was intended to provide a second opinion in regards to the degree and severity of the

deterioration of the structural support system based only on a visual inspection and a review of previous load rating analysis performed by others.

ROUTINE BRIDGE INSPECTION

A visual inspection of the asphalt overlay and railings was performed. These components were accessed by foot. A visual inspection of the girders, soffit, crossbeams, and abutments was also performed. These components were accessed by float tube.

The inspection also served to assist in determining feasible replacement options.

STRUCTURAL ANALYSIS

A load rating analysis was not performed by Kpff as part of this evaluation.

4. EVALUATION FINDINGS

BRIDGE INSPECTION

The bridge is in poor condition structurally. Most of the primary load carrying components as seen from the underside of the bridge exhibit severe concrete deterioration such as cracks, spalls, and exposed corroded reinforcement with measurable section loss. The exterior girders (A, B, E, and F) are in worse condition than the interior girders. The cap beams, which the longitudinal girders frame into, and the deck underside, which the longitudinal girders support, also exhibit evidence of advance deterioration to both the concrete and reinforcing steel.

At the east corner of the south abutment (Pier 1), material has spilled out from under the retaining wall but does not appear to be impacting the abutment. At the north abutment (Pier 5), the embankment has sloughed and material has accumulated next to Span 4 Girder B.

The bridge inspection report, component labeling system, and photographs are included in Appendix A.

STRUCTURAL ANALYSIS

The 2009 "Downtown Spokane Streetcar Alternative Analysis" report by CH2MHill found that the crossbeams do not have enough capacity to support the bridge dead load using conservative assumptions for material strengths. The longitudinal girders were deficient in shear and bending under pedestrian live load using conservative assumptions for material strengths.

5. CONCLUSIONS AND RECOMMENDATIONS

Kpff concurs that this 83 year old bridge has completed its useful service life and should be programmed for replacement. This is due to the condition of the concrete girders, caps, deck, and the undermining of Pier 2 which was temporarily repaired about 14 years ago.

Currently, a portion of the middle deck area is blocked from pedestrian use forcing the pedestrians toward the exterior concrete railing. However, we determined that the exterior girders are in worse condition than the interior

girders. Accordingly we recommend that consideration be given to restricting access to the outside area of the bridge and the interior area re-opened to pedestrian traffic.

BRIDGE REPLACEMENT OPTIONS

The bridge replacement options address visual and hydraulic clearance constraints as summarized below:

- 1) *The City Engineering Department requires the new bridge superstructure to be below deck (girder style) and not above deck (truss or arch style)*

This requires using a multiple span bridge (two or three in water piers) in order to achieve a shallow structural system.

- 2) *The City Engineering Department requires the new bridge superstructure to have a 3-foot minimum clearance above mean high water.*

On the existing bridge the bottoms of the crossbeams are below the high water mark. The new bridge must be more slender. In addition room must be made for inspection access below the bridge. This means that any new bridge superstructure depth must be minimized to provide sufficient clearance for routine bridge inspections. It also further challenges the first constraint.

- 3) *Because permitting for bridge replacements over water involve shadow effects in the river, the new bridge footprint (total area) should not be greater than the existing bridge footprint.*

Two replacement options that meet these constraints are being considered for the new Howard Street South Bridge.

The first option consists of a three-span pre-stressed voided slab superstructure. This configuration requires two in-water bents, with three columns at each bent (six total in-water columns). The footprint of the bridge matches the existing bridge layout.

The second option also uses pre-stressed voided slabs for the superstructure. This layout has three main spans in the middle of the bridge, but the ends of the bridge “flair out”. The two triangular pieces of the bridge at the south end of the bridge would be cast in place. The substructure would require at least eight in-water piers and the south abutment would be about twice as long as the abutment in option 1. This geometry was proposed by the City Parks Department to ease congestion around the fountain at the south end of the bridge.

Details and a cost estimate of the bridge replacement options are included in Appendix B. The total estimated cost for the first replacement option is \$4.4 million. The total estimated cost for the second replacement option is \$5.8 million.

Due to the age, poor construction quality, and previous scour issues, a bridge replacement option using the existing in-water piers is not recommended.

A single span structure with no interior piers is a feasible replacement option. However, our understanding is that the City Parks Department prefers that the bridge blends in with the surrounding park pedestrian paths and views a bridge with an above deck structure, such as a truss, arch, or pylon-cable system to not meet this criterion. The advantage of the above deck structural system is that it removes all piers from the water, creates an improved hydraulic cross-section, reduces scour as a design consideration, and allows for much greater access for inspection. In addition, the above deck system could promote an opportunity for creative and iconic designs that

become a visual attribute for the park. However, the costs would likely be greater than the options considered herein.

6. PERMITS AND CULTURAL RESOURCE REQUIREMENTS

PERMITS

An environmental permit matrix was prepared by SWCA Environmental Consultants for the Riverfront Park Bridges. The proposed bridge improvement work may require the following permits or approvals:

- Section 404 Nationwide Permit 14 (NWP 14) – Linear transportation projects from US Army Corps of Engineers
- Section 7 Endangered Species Act consultation from US Fish and Wildlife Service
- National Historic Preservation Act – Section 106 consultation from Washington Department of Archaeology and Historic Preservation and potentially affected tribes
- Executive Order 05-05 from Washington Department of Archaeology and Historic Preservation
- Hydraulic Project Approval permit from the Washington Department of Fish and Wildlife.
- State Environmental Policy Act Threshold Determination from the City of Spokane
- Critical Areas Review from the City of Spokane
- Shoreline Substantial Development Permit from the City of Spokane

CULTURAL RESOURCE STUDY

This bridge is not currently listed on the National Register of Historic Places (NRHP), but is eligible for NRHP status. The Howard Street Bridge replacement will require a Washington State Historic Property Inventory Form. An archeological survey will be required due to the excavation at the abutments.

For more detailed information on the permits and cultural resource requirements please see the full report prepared by SWCA Environmental Consultants.

APPENDIX A

	<u>PAGE</u>
BRIDGE INSPECTION FORM	A-1

LIST OF PHOTOGRAPHS

<u>PHOTO</u>	<u>DESCRIPTION</u>	<u>PAGE</u>
1	Howard Street South Bridge Deck (Looking North)	A-3
2	Howard Street South Bridge Elevation (Looking West)	A-3
3	Typical Soffit Condition - Map Cracking with Efflorescence/Stalactites	A-4
4	Typical Condition of Exterior Girders – Exposed/Corroded Reinforcement.....	A-4
5	Typical Condition of Girders – Horizontal Leaching Cracks	A-5
6	Material Spilling Through at South Abutment.....	A-5

	<u>PAGE</u>
BRIDGE COMPONENT LABELING SYSTEM.....	A-6



CITY OF SPOKANE

PEDESTRIAN BRIDGE INSPECTION FORM

				Bridge No.	
Bridge Name				Bridge Location	
Inspection Date		Inspector(s)		Agency	
Access Method				Weather	
Load Rating Date			Live Load	Pedestrian	Vehicle
Load Rating Factor(s)	Ped.	Veh.	Controlling Component	Pedestrian	Vehicle

Description of Bridge

--

Summary of Condition and Critical Findings

--

Summary of Recommendations

--

Summary of Bridge Condition

Bridge Component		No. of Compon.	% of **	Condition Rating*			Comments
				8 – 7 Good	6 – 5 Fair	4 – 3 Poor	
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							

*See Page 2 for detailed descriptions **Condition rating percentages are based on the % of area, length, or each of the bridge components inspected.

GENERAL NOTES

--

DESCRIPTION OF CONDITION OF BRIDGE COMPONENT		
Condition Value	Material	Description
8 – 7 Very good → Good 2 yr. insp. Cycle No repairs.	Steel	Like new, surface rust, minor pitting, no material loss. Connections are good. No damage.
	Concrete	No to minor/ insignificant defects includes: cracks, spalls, chips, consolidation, efflorescence.
	Timber	Beams: Minor splits, checks, or defects (one side), no decay or insects – sounds solid. Posts: Splits or cracks less than 3/8" (one side), no decay or insects – sounds solid.
	Paint	No defects, no sign of rust including no freckled rust, no peeling, no exposed steel.
	Scour / Erosion	None or minor.
6 – 5 Satisfactory → Fair 1 – 2 yr insp. cycle Monitor for repairs Paint: Max 10 year life estimate	Steel	Moderate corrosion, pitting, flaking, pack rust. Material loss is evident but barely measurable. Connections have up to moderate corrosion but remain fully functional. No cracks.
	Concrete	Some spalling but exposed rebar (if any) is insignificant or exhibits some surface rust; delamination is evident with or without evidence of rebar corrosion. Shear zone cracks are tight, barely measureable, and low density. Flexure zone cracks are measurable but less than .035 inch and low density. Concrete may exhibit: efflorescence (moderate to heavy), surface rust, heavy map cracking, very poor consolidation. Settlement cracks in foundations and wall are stable and less than 1/4" wide.
	Timber	Beams: Less than 3/8" splits – two sides or greater than 3/8" on one side. Some decay (max 10% by volume), some softness but sounds solid – no insects. Posts: More than 1/2 "splits – two sides or greater than 3/4" on one side. Decay is evident (greater than 20% by volume), timber may have extensive wetness and softness.
	Paint	Freckled rust, small areas of exposed steel, some peeling, oxidized.
	Scour / Erosion	Evidence of scour, exposed footing, no undermining. Banks are sloughing, protection, if any, needs repair.
4 – 3 Poor → Critical 3 mo – 1 yr. insp. cycle (as needed) Repairs needed. (ASAP or one year) Re - paint	Steel	Heavy to severe: corrosion, pitting, pack rust. Measurable material loss. Connections are heavily corroded, missing, and questionable functionality. Fatigue cracks.
	Concrete	Large spalls, deep w/ exposed and corroded rebar w/ material loss evident. Cracks are wider, closely spaced, clearly structural in nature both in shear and flexure zone. Concrete quality appears poor w/ heavy scaling, stagilites, efflorescence, map cracking, extensive surface rust and delamination, and very poor consolidation of concrete. Settlement cracks are significant.
	Timber	Beams: Greater than 3/8" on two sides. Moderate decay up to 20%, surface softness, do not sound solid – may have insects. Posts: Less than 1/2 "splits – two sides or greater than 1/2" on one side. Decay is evident (20%), wetness and soft.
	Paint	Extensive freckled rust, larger areas of exposed steel, heavily oxidized, extensive peeling.
	Scour / Erosion	Undermining or threatens undermining in a manner that could impact structure stability. Banks are heavily eroded, protection if any is non-functional.

Additional Comments by Component Number

Bridge Comp. No.	Comments



Photo 1 –Howard Street South Bridge Deck (Looking North)



Photo 2 – Howard Street South Bridge Elevation (Looking West)



Photo 3 – Typical Soffit Condition - Map Cracking with Efflorescence/Stalactites




Photo 4 – Typical Condition of Exterior Girders – Exposed/Corroded Reinforcement



Photo 5 – Typical Condition of Girders – Horizontal Leaching Cracks




Photo 6 – Material Spilling Through at South Abutment




Bridge Component Labeling System

APPENDIX B


IMPROVEMENT DETAILS COST ESTIMATES




PLAN — REMOVAL



PLAN REPLACEMENT — OPTION #1
PRESTRESSED VOIDED SLABS



ELEVATION — REMOVAL




ELEVATION REPLACEMENT — OPTION #1

Name: Tautel Date: Nov 11, 2014-11:46:33am File: V:\114176 (Spokane River Front Bridges)\Howard St South Bridge\Design\HS-501.dwg

<table><tr><td colspan="2">REVISIONS</td><td colspan="2">AS BUILT</td><td colspan="2">GRADE ORDINANCE LIST</td><td colspan="2">NAVD88 DATUM</td></tr><tr><td>DATE</td><td>BY</td><td>PROJ</td><td>DESCRIPTION</td><td>DATE</td><td>BY</td><td>PROJ</td><td>E.F.N. U.S.N.</td><td>FROM</td><td>TO</td><td>COUNCIL ACCEPT DATE</td><td>FROM</td><td>TO</td><td>ORD. NO.</td><td>DATE</td><td>FILE NO.</td></tr></table>										REVISIONS		AS BUILT		GRADE ORDINANCE LIST		NAVD88 DATUM		DATE	BY	PROJ	DESCRIPTION	DATE	BY	PROJ	E.F.N. U.S.N.	FROM	TO	COUNCIL ACCEPT DATE	FROM	TO	ORD. NO.	DATE	FILE NO.	<table><tr><td colspan="2">NAVD88 — (ADD CBM ELEV.) — (11.13)</td><td colspan="2">AS OF JANUARY, 2000 USE NORTH AMERICAN VERTICAL DATUM OF 1988 (NAVD88)</td></tr><tr><td colspan="2">BENCH MARK LOCATION</td><td colspan="2">-</td></tr><tr><td colspan="2">NAVD88 ELEV.</td><td colspan="2">-</td></tr><tr><td colspan="2">CBM NO.</td><td colspan="2">-</td></tr><tr><td colspan="2">DATE IS ONE INCH ON ORIGINAL DRAWING</td><td colspan="2">HORIZONTAL PLAN/PROFILE AS SHOWN</td></tr><tr><td colspan="2">IF NOT ONE INCH ON THIS SHEET, ADJUST SCALES ACCORDINGLY</td><td colspan="2">VERTICAL PROFILE ONLY</td></tr><tr><td colspan="2">SCALE</td><td colspan="2">BY</td><td colspan="2">DATES</td></tr><tr><td colspan="2"></td><td colspan="2">DRAWN: HT</td><td colspan="2">1/1/4</td></tr><tr><td colspan="2"></td><td colspan="2">REVISED: MLF</td><td colspan="2">1/1/4</td></tr><tr><td colspan="2"></td><td colspan="2">CHECKED: TW</td><td colspan="2">1/1/4</td></tr><tr><td colspan="2"></td><td colspan="2">APPROVED: MLF</td><td colspan="2">1/1/4</td></tr></table>										NAVD88 — (ADD CBM ELEV.) — (11.13)		AS OF JANUARY, 2000 USE NORTH AMERICAN VERTICAL DATUM OF 1988 (NAVD88)		BENCH MARK LOCATION		-		NAVD88 ELEV.		-		CBM NO.		-		DATE IS ONE INCH ON ORIGINAL DRAWING		HORIZONTAL PLAN/PROFILE AS SHOWN		IF NOT ONE INCH ON THIS SHEET, ADJUST SCALES ACCORDINGLY		VERTICAL PROFILE ONLY		SCALE		BY		DATES				DRAWN: HT		1/1/4				REVISED: MLF		1/1/4				CHECKED: TW		1/1/4				APPROVED: MLF		1/1/4		<table><tr><td colspan="2">CITY OF SPOKANE, WASHINGTON</td><td colspan="2">DEPARTMENT OF ENGINEERING SERVICES</td><td colspan="2">808 WEST SPOKANE FALLS BLVD.</td><td colspan="2">SPOKANE, WASHINGTON 99201-3343</td><td colspan="2">(509) 625-6700</td></tr><tr><td colspan="2">CITY OF SPOKANE</td><td colspan="2">CITY OF SPOKANE</td><td colspan="2">CITY OF SPOKANE</td><td colspan="2">CITY OF SPOKANE</td><td colspan="2">CITY OF SPOKANE</td></tr></table>										CITY OF SPOKANE, WASHINGTON		DEPARTMENT OF ENGINEERING SERVICES		808 WEST SPOKANE FALLS BLVD.		SPOKANE, WASHINGTON 99201-3343		(509) 625-6700		CITY OF SPOKANE		CITY OF SPOKANE		CITY OF SPOKANE		CITY OF SPOKANE		CITY OF SPOKANE		<table><tr><td colspan="2">PROJECT NAME:</td><td colspan="2">RIVERFRONT PARK BRIDGES</td></tr><tr><td colspan="2">BRIDGE NAME:</td><td colspan="2">HOWARD STREET SOUTH BRIDGE REPLACEMENT</td><td colspan="2">TYPE OF IMPROVEMENT:</td><td colspan="2">BRIDGE</td></tr><tr><td colspan="2">CITY PROJECT NUMBER:</td><td colspan="2">2013186</td><td colspan="2">PLAN NUMBER:</td><td colspan="2">1 of 3</td></tr><tr><td colspan="2">PLAN AND ELEVATION</td><td colspan="2"></td><td colspan="2">ETN: ...</td><td colspan="2"></td></tr></table>										PROJECT NAME:		RIVERFRONT PARK BRIDGES		BRIDGE NAME:		HOWARD STREET SOUTH BRIDGE REPLACEMENT		TYPE OF IMPROVEMENT:		BRIDGE		CITY PROJECT NUMBER:		2013186		PLAN NUMBER:		1 of 3		PLAN AND ELEVATION				ETN: ...			
REVISIONS		AS BUILT		GRADE ORDINANCE LIST		NAVD88 DATUM																																																																																																																																																															
DATE	BY	PROJ	DESCRIPTION	DATE	BY	PROJ	E.F.N. U.S.N.	FROM	TO	COUNCIL ACCEPT DATE	FROM	TO	ORD. NO.	DATE	FILE NO.																																																																																																																																																						
NAVD88 — (ADD CBM ELEV.) — (11.13)		AS OF JANUARY, 2000 USE NORTH AMERICAN VERTICAL DATUM OF 1988 (NAVD88)																																																																																																																																																																			
BENCH MARK LOCATION		-																																																																																																																																																																			
NAVD88 ELEV.		-																																																																																																																																																																			
CBM NO.		-																																																																																																																																																																			
DATE IS ONE INCH ON ORIGINAL DRAWING		HORIZONTAL PLAN/PROFILE AS SHOWN																																																																																																																																																																			
IF NOT ONE INCH ON THIS SHEET, ADJUST SCALES ACCORDINGLY		VERTICAL PROFILE ONLY																																																																																																																																																																			
SCALE		BY		DATES																																																																																																																																																																	
		DRAWN: HT		1/1/4																																																																																																																																																																	
		REVISED: MLF		1/1/4																																																																																																																																																																	
		CHECKED: TW		1/1/4																																																																																																																																																																	
		APPROVED: MLF		1/1/4																																																																																																																																																																	
CITY OF SPOKANE, WASHINGTON		DEPARTMENT OF ENGINEERING SERVICES		808 WEST SPOKANE FALLS BLVD.		SPOKANE, WASHINGTON 99201-3343		(509) 625-6700																																																																																																																																																													
CITY OF SPOKANE		CITY OF SPOKANE		CITY OF SPOKANE		CITY OF SPOKANE		CITY OF SPOKANE																																																																																																																																																													
PROJECT NAME:		RIVERFRONT PARK BRIDGES																																																																																																																																																																			
BRIDGE NAME:		HOWARD STREET SOUTH BRIDGE REPLACEMENT		TYPE OF IMPROVEMENT:		BRIDGE																																																																																																																																																															
CITY PROJECT NUMBER:		2013186		PLAN NUMBER:		1 of 3																																																																																																																																																															
PLAN AND ELEVATION				ETN: ...																																																																																																																																																																	

REGION NO.	STATE	FEDERAL AID PROJECT NO.	SHEET NO.
EASTERN	WASH.	---	



TYPICAL SECTION REPLACEMENT – OPTION #1



TYPICAL SECTION EXISTING BRIDGE

[illegible]

NAVDSB = 000 000 000 7 7 1 7 1 3 1 3		AS OF JANUARY, 2000 USE NORTH AMERICAN CYRILLIC DILUIM 00 1300 (NAVDSB)	
BENCH MARK LOCATION			
		CURRENT C.O.S. DRAFTING STANDARDS ADOPTED FEB. 2007	
NAVDSB: ELEV.	BAR IS ONE INCH ON ORIGINAL DRAWING	HORIZONTAL PLANIMETER	BY
		AS SHOWN	DATES
SCALE NO.	IF NOT ONE INCH ON THIS SHEET, ADJUST SCALES ACCORDINGLY	VERTICAL PLANIMETER	HT
NAVDSB DATUM		ONLY	1/1/14
		SCALE	REVISED: MUF
			1/1/14 TW
			APPROVED: MUF
			1/1/14






CITY OF SPOKANE, WASHINGTON
DEPARTMENT OF ENGINEERING SERVICES
808 WEST SPOKANE FALLS BLVD.
SPOKANE, WASHINGTON 99201-3343
(509) 625-6700

PROJECT NAME:			RIVERFRONT PARK BRIDGES		
BRIDGE NAME:			TYPE OF IMPROVEMENT:		BRIDGE
HOWARD STREET SOUTH BRIDGE REPLACEMENT			CITY PROJECT NUMBER:		PLAN NUMBER:
			2013186		2 of 3
TYPICAL SECTION			EFT#:		---

name: TaulieA Date: Nov 11, 2014-11:46:24am File: V:\114176 (Spokane River Front Bridges)\Howard St South Bridge\Design\HS-S02.dwg

Name: Tounet Date: Nov 11, 2014-11:46:46am File: V:\114176 (Spokane River Front Bridges)\Howard St. South Bridge\Design\HS-503.dwg

REGION NO.	STATE	FEDERAL AID PROJECT NO.	SHEET NO.
EASTERN	WASH.	---	---



DATE	BY	PROJ.	DESCRIPTION	DATE	BY	PROJ.	DESCRIPTION	DATE	BY	PROJ.	DESCRIPTION

NAVDS - (ADD CBM ELEV.) - (11.13)	AS OF JANUARY, 2000 USE NORTH AMERICAN VERTICAL DATUM OF 1988 (NAVDS)
BENCH MARK LOCATION	
NAVDS ELEV.	
CBM NO.	
DATE	
FROM	
TO	
ORD. NO.	
DATE	
FILE NO.	

CITY OF SPOKANE, WASHINGTON	DEPARTMENT OF ENGINEERING SERVICES
808 WEST SPOKANE FALLS BLVD.	SPOKANE, WASHINGTON 99201-3343
(509) 625-6700	

PROJECT NAME:	RIVERFRONT PARK BRIDGES
BRIDGE NAME:	HOWARD STREET SOUTH BRIDGE REPLACEMENT
TYPE OF IMPROVEMENT:	BRIDGE
CITY PROJECT NUMBER:	2013186
PLAN NUMBER:	3 of 3

Cost Estimates for Bridge Improvements Based on the 2014 KPFF Inspection and Analysis Recommendations

Bridge Name: Howard Street South Bridge Option 1
 Bridge Length and Width (feet) 205 71

Recommendations for Improvements - Include: Replace existing bridge with a 3-span structure on similar footprint

Item no	Item Description	Cost Unit	Quantity	Unit Cost	Item Cost
1	Remove existing structure(s)	SQ FT	13135	30	\$ 394,050
2	Precast Conc Girders	LF	3639	300	\$ 1,091,625
3	5 " concrete deck overlay	CUYD	225	750	\$ 168,461
4	Concrete Piers	CUYD	150	1000	\$ 150,000
5	Pile Foundations (Abut & Piers)	EA	44	5000	\$ 220,000
6	Concrete Abutments & Wingwalls (2)	CUYD	200	1000	\$ 200,000
7	Bridge Railing (aesthetic)	LF	410	200	\$ 82,000
8	Bearings -Exp Joints - Drainage	LS	1	150000	\$ 150,000
9	Landscaping and Bank Enhancements	LS	1	50000	\$ 50,000
Total					\$ 2,506,136
10	Mobilization	10%			\$ 250,614
11	Design, Permits, Hydraulic, Geotech, Survey	15%			\$ 375,920
12	Construction Management	13%			\$ 313,267
13	Taxes	8%			\$ 200,491
14	Contingency	30%			\$ 751,841
15	Excalation (1 year)	3%			\$ 75,184
16	Agency Project Development & Mngmt.	5%			\$ 125,307
Total					\$ 2,092,623
Total Project Cost (2015)					\$ 4,598,759
Square Foot Cost (\$/SF)					\$ 316

Cost Estimates for Bridge Improvements Based on the 2014 KPFF Inspection and Analysis Recommendations

Bridge Name: Howard Street South Bridge Option 2
 Bridge Length and Width (feet) 205 varies

Recommendations for Improvements - Include: Replace existing bridge with a 3-span structure with "flaired" approach spans

Item no	Item Description	Cost Unit	Quantity	Unit Cost	Item Cost
1	Remove existing structure(s)	SQ FT	13135	30	\$ 394,050
2	Precast Conc Girders	LF	3639	375	\$ 1,364,531
3	5 " concrete deck overlay	CUYD	225	750	\$ 168,461
4	Concrete Piers	CUYD	225	1000	\$ 225,000
5	Pile Foundations (Abut & Piers)	EA	66	5000	\$ 330,000
6	Concrete Abutments & Wingwalls (2)	CUYD	300	1000	\$ 300,000
7	Bridge Railing (aesthetic)	LF	480	260	\$ 124,800
8	Bearings -Exp Joints - Drainage	LS	1	225000	\$ 225,000
9	Landscaping and Bank Enhancements	LS	1	75000	\$ 75,000
Total					\$ 3,206,842
10	Mobilization	10%			\$ 320,684
11	Design, Permits, Hydraulic, Geotech, Survey	15%			\$ 481,026
12	Construction Management	13%			\$ 400,855
13	Taxes	8%			\$ 256,547
14	Contingency	30%			\$ 962,053
15	Excalation (1 year)	3%			\$ 96,205
16	Agency Project Development & Mngmt.	5%			\$ 160,342
Total					\$ 2,677,713
Total Project Cost (2015)					\$ 5,884,555
Square Foot Cost (\$/SF)					\$ 404

APPENDIX C

PHOTOGRAPH LOG

PHOTOGRAPH CONTACT SHEET

Date of Inspection: 8/13/2014

C-1

Howard Street Bridge South Channel Photographs



IMG_1991.JPG



IMG_0920.JPG



IMG_0921.JPG



IMG_0922.JPG



IMG_0923.JPG




IMG_0924.JPG



IMG_0925.JPG



IMG_0926.JPG



IMG_0927.JPG



IMG_0928.JPG



IMG_0929.JPG



IMG_0930.JPG



IMG_0931.JPG



IMG_0932.JPG



IMG_0933.JPG




IMG_0934.JPG



IMG_0939.JPG



IMG_0940.JPG



IMG_0941.JPG



IMG_0942.JPG



IMG_0944.JPG



IMG_0945.JPG



IMG_0946.JPG



IMG_0947.JPG



IMG_0948.JPG



IMG_0949.JPG



IMG_0950.JPG



IMG_1989.JPG



IMG_1990.JPG