

Bridge Condition Assessment

Arch and Spandrels

- Main arch and spandrels have high capacity
- Deterioration of spandrels has minimal effect on capacity



Two arch ribs each side



Minor cracking in main ribs



Spandrel column deterioration



Spandrel column deterioration